

7181

U-007-305.94

OU 5 SOUTH FIELD PUMP TEST REPORT

09/14/95

USEPA	DOE-FN
1	
COMMENTS	



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, IL 60604-3590

7181
FERNALD

LOG

I-3634
SEP 18 10 59 AM '95

SEP 14 1995

REPLY TO THE ATTENTION OF:

LIBRARY: WRE-BJ

Mr. Jack R. Craig
United States Department of Energy
Feed Materials Production Center
P.O. Box 398705
Cincinnati, Ohio 45239-8705

RE: OU 5 South Field Pump Test
Report

Dear Mr. Craig:

The United States Environmental Protection Agency (U.S. EPA) has completed its review of the Operable Unit (OU) 5 South Field Pump Test report. The report documents the step drawdown and constant rate pumping tests conducted to determine aquifer characteristics in the South Field area.

The pumping tests were conducted in a technically correct manner and the results should provide accurate information for the groundwater model.

Therefore, U.S. EPA hereby approves the OU 5 South Field pump test report.

Please contact me at (312) 886-0992 if you have any questions regarding this matter.

Sincerely,

James A. Saric, Remedial Project Manager
Technical Enforcement Section #1
RCRA Enforcement Branch

cc: Tom Schneider, OEPA-SWDO
Jack Baublitz, U.S. DOE-HDQ
Don Ofte, FERMCO
Charles Little, FERMCO
Terry Hagen, FERMCO
Michael Yates, FERMCO